


FIG. 1



**FIG. 2**




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

## Search Screen

**Spectrocolorimeter**

**Specular state Excl. / Incl.**

**UV state Excl. / Incl.**

**CIE Standard Observer 1931 / 1961**

**Illuminant**   
These fields could be replaced with  
references to a color selection guide or  
CIELAB coordinates for searching  
**1**   
**2**   
**3**

**Color Tolerance Equation and Parameters**

**Ink range**

**Printing process (offset/flexo etc.)**

**Substrate**

**After processing (varnished/laminated etc.)**

**Customer**

**Advanced search**  (see next page)

**Calibrate**

**Measure**